

System Rejuvenation on Tight Site on Whaley Lake, Dutchess County, New York



Problem: Failing metal septic tank in need of a rejuvenated leach field on a beautiful recreation lake in Dutchess County NY.

- Sloping site with a small footprint
- System within 30' of lake edge
- Replacing failed old metal tank
- Dispersal into existing leaching pits

Solution: Use a lightweight and small footprint FujiClean advanced treatment unit to discharge highly treated & oxygenated effluent into existing leach pit for rejuvenation.

- FujiClean Model CE5 (Hydraulic design capacity; 500-gpd)
- Proven treatment results of BOD <15 mg/L and TSS <15 mg/L
- One tank treatment with tiny footprint and low profile (85"L x 44"W x 62"H)
- Lightweight (<400 lbs.) easy to maneuver into location

Designer & Installer: Tyndall Septic Systems, Brewster, NY

Adapted from Onsite Installer Magazine, December 2022